


Part: AM79C972BVI
MFG: ADVANCED MICRO
DEVICES INC
D/C: 1040
L/C:
Origin: Korea
Status: SC
Reported: 11/23/2015



**Remarking & Resurfacing Testing Revealed:
Parts Failed Resistance To Solvents (RTS) -
Acetone**

Surface material was removed using acetone
(e.g. CAS Registry Number 67-64-1)
Previous part markings (e.g. ghost markings)
visible after test

FEATURE SPOTLIGHT: Nonconformance Photo Library/Training Slideshow

Searching for reference photographs of nonconforming and suspect counterfeit parts? Have a new employee to train?

ERAI Members can cull the library of photographs from our High Risk & Suspect Counterfeit Parts Database to create slideshow presentations based on search criteria from the Nonconformance Photo Library. You can locate images of specific part non-conformances from a list of categories displayed in our Nonconformance Photo Library and can further drill down to specific part numbers or parts from a selected manufacturer – whatever best suits your individual needs.

Company Administrators can also create stand-alone slideshows. These slideshows are custom-made upon request and will provide you with an encoded link that will launch the slideshow on any computer that has a browser and Internet connection.

To create your own slideshow, visit:

http://www.era.com/Nonconformance_Photo_Library

or call the ERAI IT Department at 239-261-6268.

